


Pin Header Connectors

TOPTEK®

HARDWARE ELECTRONIC MANUFACTURER




www.toptek-co.com

TOPTEK srl
10015 - IVREA (TO) - ITALY
tel. +39 0125 251 211 - fax +39 0341 367 607
info@toptek-co.com




Pitch 0.8mm



PH6DM 14 - 2 XX - U
1 2 3

1.H=1.4mm
2.No. of Contacts(03~50)
3.RoHS + Nylon 6T


Pitch 0.8mm



PH6S 14 - 2 XX - U
1 2 3

1.H=1.4mm
2.No. of Contacts(03~50)
3.RoHS + Nylon 6T


Pitch 0.8mm



PH6D 14 - 2 XX - U
1 2 3

1.H=1.4mm
2.No. of Contacts(03~50)
3.RoHS + Nylon 6T


Pitch 0.8mm



PS6M31 - 2 XX - U
1 2

H=3.1mm
1.No. of Contacts(03~50)
2.RoHS + Nylon 6T

Pitch 1.0mm



PH5M XX - 2 XX - U
1 2 3

1.H=1.0mm No. of Contacts(02~50)
2.H=1.5mm No. of Contacts(02~40)
3.RoHS + Nylon 6T

Pitch 1.0mm



PH5DM XX - 2 XX - U
1 2 3

1.H=1.0mm No. of Contacts(02~50)
2.H=1.5mm No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 1.0mm



PH5R XX - 2 XX - U
1 2 3

1.H=1.0mm No. of Contacts(02~50)
2.H=1.5mm No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 1.0mm



PH5R 10 - 1 XX - U
1 2 3

1.H=1.0mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T


Pitch 1.0mm



PH5S XX - 2 XX - U
1 2 3

1.H=1.0mm No. of Contacts(02~50)
2.H=1.5mm No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 1.0mm



PH5S 10 - 1 XX - U
1 2 3

1.H=1.0mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T


Pitch 1.0mm



PH5D XX - 2 XX - U
1 2 3

1.H=1.0mm No. of Contacts(02~50)
2.H=1.5mm No. of Contacts(02~40)
3.RoHS + Nylon 6T

Pitch 1.0mm



PH5D 10 - 1 XX - U
1 2 3

1.H=1.0mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

CONNECTORS MANUFACTURER

TOPTEK®
HARDWARE ELECTRONIC MANUFACTURER




2 * 2

Pin Header / Female 1.0 - 1.27 mm



RoHS

Pitch 1.0mm



PS5M 21 - 2 XX - U
1 2 3

1.H=2.1mm
2.No. of Contacts(03~50)
3.RoHS + Nylon 6T


Pitch 1.27mm SQ Pin=0.4mm



PH3M XX - 2 XX - U
1 2 3

1.H=0.85/1.0/1.5/1.7/2.0/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T


Pitch 1.27mm SQ Pin=0.4mm



PH3DM XX - 2 XX - U
1 2 3

1.H=0.85/1.0/1.5/1.7/2.0/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T


Pitch 1.27mm SQ Pin=0.4mm



PH3M XX - 1 XX - U
1 2 3

1.H=1.0/1.5/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 1.27mm SQ Pin=0.4mm



PH3DM XX - 1 XX - U
1 2 3

1.H=1.0/1.5/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T


Pitch 1.27mm SQ Pin=0.4mm



PH3R XX - 2 XX - U
1 2 3

1.H=0.85/1.0/1.5/1.7/2.0/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T


Pitch 1.27mm SQ Pin=0.4mm



PH3R XX - 1 XX - U
1 2 3

1.H=1.0/1.5/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T


Pitch 1.27mm SQ Pin=0.4mm



PH3S XX - 2 XX - U
1 2 3

1.H=0.85/1.0/1.5/1.7/2.0/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T


Pitch 1.27mm SQ Pin=0.4mm



PH3S XX - 1 XX - U
1 2 3

1.H=1.0/1.5/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T


Pitch 1.27mm SQ Pin=0.4mm



PH3D XX - 2 XX - U
1 2 3

1.H=0.85/1.0/1.5/1.7/2.0/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T


Pitch 1.27mm SQ Pin=0.4mm



PH3D XX - 1 XX - U
1 2 3

1.H=1.0/1.5/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 1.27mm SQ Pin=0.46mm



PH4M XX - 2 XX - U
1 2 3

1.H=1.7/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 1.27mm SQ Pin=

PH4DM XX - 2 XX - U
1 2 3

1.H=1.7/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 1.27mm SQ Pin=0.46mm

PH4M XX - 1 XX - U
1 2 3

1.H=1.7/2.0/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 1.27mm SQ Pin=0.46mm

PH4DM XX - 1 XX - U
1 2 3

1.H=1.7/2.0/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 1.27mm SQ Pin=0.46mm

PH4R XX - 2 XX - U
1 2 3

1.H=1.7/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 1.27mm SQ Pin=0.46mm

PH4R XX - 1 XX - U
1 2 3

1.H=1.7/2.0/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 1.27mm SQ Pin=0.46mm

PH4S XX - 2 XX - U
1 2 3

1.H=1.7/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 1.27mm SQ Pin=0.46mm

PH4S XX - 1 XX - U
1 2 3

1.H=1.7/2.0/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 1.27mm SQ Pin=0.46mm

PH4D XX - 2 XX - U
1 2 3

1.H=1.7/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 1.27mm SQ Pin=0.46mm

PH4D XX - 1 XX - U
1 2 3

1.H=1.7/2.0/2.5mm
2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 1.27x1.27mm

BH3 X - XX - U
1 2 3

1.S: Straight M: SMT
2.No. of Contacts(10~80)
3.RoHS + Nylon 6T

Pitch 1.27x1.27mm

BH3C X - XX - U
1 2 3

1.S: Straight M: SMT R: R/A
2.No. of Contacts(10~100)
3.RoHS + Nylon 6T

Pitch 1.27x1.27mm

BH3E X - XX - U
1 2 3

1.S: Straight M: SMT
2.No. of Contacts(06~100)
3.RoHS + Nylon 6T

CONNECTORS MANUFACTURER

TOPTEK®
HARDWARE ELECTRONIC MANUFACTURER



2
*
4

P in Header / Female 1.27 mm



RoHS

Pitch 1.27x2.54mm



BH4 X - XX - U
1 2 3

1.S: Straight M: SMT R: R/A
2.No. of Contacts(06~100)
3.RoHS + Nylon 6T

Pitch 1.27x1.27mm



EDH3 X - XX - U
1 2 3

1.S: Straight M: SMT R: R/A
2.No. of Contacts(06~100)
3.RoHS + Nylon 6T

Pitch 1.27x2.54mm



EDH4S - XX - L
1 2

1.No. of Contacts(06~100)
2.RoHS + PBT

Pitch 1.27x1.27mm



PS3BM 20 - 2 XX - U
1 2 3

1.H=2.0mm
2.No. of Contacts(03~50)
3.RoHS + Nylon 6T


Pitch 1.27mm



PS3BM XX - 1 XX - U
1 2 3

1.H=2.1/3.4/4.4mm
2.No. of Contacts(03~50)
3.RoHS + Nylon 6T


Pitch 1.27x1.27mm



PS3M XX - 2 XX - U
1 2 3

1.H=2.0/3.4/4.4mm
2.No. of Contacts(03~50)
3.RoHS + Nylon 6T


Pitch 1.27x1.27mm



PS3M 21 - 2 XX - U
1 2 3

1.H=2.1mm
2.No. of Contacts(03~50)
3.RoHS + Nylon 6T


Pitch 1.27mm



PS3M XX - 1 XX - U
1 2 3

1.H=2.1/3.4/4.4mm
2.No. of Contacts(03~50)
3.RoHS + Nylon 6T


Pitch 1.27x1.27mm



PS3R 44 - 2 XX - U
1 2 3

1.H=4.4mm
2.No. of Contacts(03~50)
3.RoHS + Nylon 6T


Pitch 1.27mm



PS3R 44 - 1 XX - U
1 2 3

1.H=4.4mm
2.No. of Contacts(03~50)
3.RoHS + Nylon 6T


Pitch 1.27x1.27mm



PS3S 44 - 2 XX - U
1 2 3

1.H=4.4mm
2.No. of Contacts(03~50)
3.RoHS + Nylon 6T

Pitch 1.27mm



PS3S 44 - 1 XX - U
1 2 3

1.H=4.4mm
2.No. of Contacts(03~50)
3.RoHS + Nylon 6T



Pitch 1.27x1.27mm



PS3MS - 2 XX - U
1 2

H=3.45mm
1.No. of Contacts(03~50)
2.RoHS + Nylon 6T


Pitch 1.27x1.27mm



PS3RS - 2 XX - U
1 2

H=3.45mm
1.No. of Contacts(03~50)
2.RoHS + Nylon 6T


Pitch 1.27x2.54mm



PS4M58 - 2 XX - U
1 2

H=5.7mm
1.No. of Contacts(03~50)
2.RoHS + Nylon 6T

Pitch 1.27mm



PS4M58 - 1 XX - U
1 2

H=5.7mm
1.No. of Contacts(03~50)
2.RoHS + Nylon 6T

Pitch 1.27x2.54mm



PS4S46 - 2 XX - U
1 2

H=4.6mm
1.No. of Contacts(03~50)
2.RoHS + Nylon 6T


Pitch 1.27mm



PS4S46 - 1 XX - U
1 2

H=4.6mm
1.No. of Contacts(03~50)
2.RoHS + Nylon 6T


Pitch 1.27x2.54mm



PS4S85 - 2 XX - U
1 2

H=8.5mm
1.No. of Contacts(03~50)
2.RoHS + Nylon 6T


Pitch 1.27mm



PS4S85 - 1 XX - U
1 2

H=8.5mm
1.No. of Contacts(03~50)
2.RoHS + Nylon 6T


Pitch 1.27mm



MJ3P - X - L
1 2

1.A:Close 3.0mm D:With handle 5.5mm
E:MULTI-POST
2.RoHS + Nylon 66


Pitch 2.0mm



PH2M XX - 2 XX - U
1 2 3

1.H=1.5mm 2.No. of Contacts(02~50)
H=2.0mm 2.No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 2.0mm



PH2DM XX - 2 XX - U
1 2 3

1.H=1.5mm 2.No. of Contacts(02~50)
H=2.0mm 2.No. of Contacts(02~40)
3.RoHS + Nylon 6T

Pitch 2.0mm



PH2M XX - 1 XX - U
1 2 3

1.H=1.5mm 2.No. of Contacts(02~50)
H=2.0mm 2.No. of Contacts(02~40)
3.RoHS + Nylon 6T

CONNECTORS MANUFACTURER

TOPTEK®
HARDWARE ELECTRONIC MANUFACTURER



2
*
6

P in Header / Female 2.0 mm

P

Pb

RoHS

Pitch 2.0mm



PH2DM XX - 1 XX - U
1 2 3

1.H=1.5mm 2.No. of Contacts(02~50)
H=2.0mm 2.No. of Contacts(02~40)
3.RoHS + Nylon 6T

Pitch 2.0mm



PH2MR XX - 2 XX - U
1 2 3

1.H=1.5mm 2.No. of Contacts(02~50)
H=2.0mm 2.No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 2.0mm



PH2MR XX - 1 XX - U
1 2 3

1.H=1.5mm 2.No. of Contacts(02~50)
H=2.0mm 2.No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 2.0mm



PH2R XX - 2 XX - L/U
1 2 3

1.H=1.5mm 2.No. of Contacts(02~50)
H=2.0mm 2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.0mm



PH2R XX - 1 XX - L/U
1 2 3

1.H=1.5mm 2.No. of Contacts(02~50)
H=2.0mm 2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.0mm



PH2S XX - 2 XX - L/U
1 2 3

1.H=1.5mm 2.No. of Contacts(02~50)
H=2.0mm 2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.0mm



PH2S XX - 1 XX - L/U
1 2 3

1.H=1.5mm 2.No. of Contacts(02~50)
H=2.0mm 2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.0mm



PH2D XX - 2 XX - L/U
1 2 3

1.H=1.5mm 2.No. of Contacts(02~50)
H=2.0mm 2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.0mm



PH2D XX - 1 XX - L/U
1 2 3

1.H=1.5mm 2.No. of Contacts(02~50)
H=2.0mm 2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.0mm



PH2S/R 40 - 2 XX - L/U
1 2 3

1.H=4.0mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.0mm



BH2 S/R/M - XX - L/U
1 2 3

1.Straight/Right Angle/SMT
2.No. of Contacts(06~68)
3.RoHS + PBT/Nylon 6T

Pitch 2.0mm




BH2A S/R/M - XX - L/U
1 2 3

1.Straight/Right Angle/SMT
2.No. of Contacts(06~68)
3.RoHS + PBT/Nylon 6T




Pitch 2.0mm



BH2B S/M - XX - U
1 2 3

1. Straight/SMT
2. No. of Contacts(04~100)
3. RoHS + Nylon 6T

Pitch 2.0mm



BH2E S/M - XX - L/U
1 2 3

1. Straight/SMT
2. No. of Contacts(06~68)
3. RoHS + PBT/Nylon 6T

Pitch 2.0mm



EDH2 S/R/M - XX - 1 - U
1 2 3

1. Straight/Right Angle/SMT
2. No. of Contacts(10~64)
3. RoHS + Nylon 6T


Pitch 2.0mm



EDH2E S/R/M - XX - U
1 2 3

1. Straight/Right Angle/SMT
2. No. of Contacts(10~64)
3. RoHS + Nylon 6T


Pitch 2.0mm



PS2M XX - 2 XX - U
1 2 3

1. H=2.1/2.8mm
2. No. of Contacts(02~40)
3. RoHS + Nylon 6T


Pitch 2.0mm



PS2M XX - 2 XX - U
1 2 3

1. H=4.0/4.3/4.6mm
2. No. of Contacts(02~40)
3. RoHS + Nylon 6T


Pitch 2.0mm



PS2M 27 B - 2 XX - U
1 2 3

1. H=2.7mm
2. No. of Contacts(02~40)
3. RoHS + Nylon 6T


Pitch 2.0mm



PS2M 63 - 2 XX - U
1 2 3

1. H=6.35mm
2. No. of Contacts(02~40)
3. RoHS + Nylon 6T


Pitch 2.0mm



PS2M XX - 1 XX - U
1 2 3

1. H=4.0/4.3/4.6mm
2. No. of Contacts(02~40)
3. RoHS + Nylon 6T


Pitch 2.0mm



PS2S XX - 1/2 XX - L/U
1 2 3

1. H=4.0/4.3/4.6mm
2. No. of Contacts(02~40)
3. RoHS + PBT/Nylon 6T


Pitch 2.0mm



PS2SB XX - 2 XX - L/U
1 2 3

1. H=4.0/4.3mm
2. No. of Contacts(02~40)
3. RoHS + PBT/Nylon 6T

Pitch 2.0mm



PS2S43B - 2 XX - L/U
1 2

H=4.3mm
1. No. of Contacts(02~40)
2. RoHS + PBT/Nylon 6T

CONNECTORS MANUFACTURER

TOPTEK®
HARDWARE ELECTRONIC MANUFACTURER



2 * 8


Pin Header / Female 2.0 - 2.54 mm

P

Pb

RoHS


Pitch 2.0mm



PS2S43B - 1 XX - L/U
1 2

H=4.3mm
1.No. of Contacts(02~40)
2.RoHS + PBT/Nylon 6T


Pitch 2.0mm



PS2R49 - 2 XX - L/U
1 2

H=4.9mm
1.No. of Contacts(02~40)
2.RoHS + PBT/Nylon 6T


Pitch 2.0mm



PS2R43 - 1 XX - L/U
1 2

H=4.3mm
1.No. of Contacts(02~40)
2.RoHS + PBT/Nylon 6T

Pitch 2.0mm



PS2R63 - 1/2 XX - L/U
1 2

H=6.3mm
1.No. of Contacts(02~40)
2.RoHS + PBT/Nylon 6T


Pitch 2.0mm



PS2S63 - 1/2/3/4 XX - L/U
1 2

H=6.3mm
1.No. of Contacts(02~40)
2.RoHS + PBT/Nylon 6T


Pitch 2.0mm



PS2E - 2/4 XX - L/U
1 2

2 & 4 rows
1.No. of Contacts(02~40)
2.RoHS + PBT/Nylon 6T


Pitch 2.0mm



PS2XS - 2 XX - L/U
1 2 3

1.MS:SMT RS:DIP
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.0mm



MJ2 P - X - L
1 2 3

1.P:Phosphor Bronze
2.B:Open 3.5mm C:Close 5.0mm D:Open 4.5mm
F:With handle 11.0mm G:With handle 9.5mm
3.RoHS + PBT(F & G Type RoHS + Nylon 66)

Pitch 2.0mm



MJ2 P - E 2 X - L
1 2 3

1.P:Phosphor Bronze
2.No. of Contacts(02~10)
3.RoHS + PBT


Pitch 2.54mm



PH1M XX - 2 XX - U
1 2 3

1.H=1.5/1.7mm 2.No. of Contacts(02~40)
H=2.5mm 2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 2.54mm



PH1DM XX - 2 XX - U
1 2 3

1.H=1.5/1.7mm 2.No. of Contacts(02~40)
H=2.5mm 2.No. of Contacts(02~50)
3.RoHS + Nylon 6T

Pitch 2.54mm



PH1M XX - 1 XX - U
1 2 3

1.H=1.5/1.7mm 2.No. of Contacts(02~40)
H=2.5mm 2.No. of Contacts(02~50)
3.RoHS + Nylon 6T



Pitch 2.54mm



PH1DM XX - 1 XX - U
1 2 3

1.H=1.5/1.7mm 2.No. of Contacts(02~40)
H=2.5mm 2.No. of Contacts(02~50)
3.RoHS + Nylon 6T


Pitch 2.54mm



PH1MR - 2 XX - U
1 2

H=2.5mm
1.No. of Contacts(02~40)
2.RoHS + Nylon 6T

Pitch 2.54mm



PH1MR - 1 XX - U
1 2

H=2.5mm
1.No. of Contacts(02~40)
2.RoHS + Nylon 6T

Pitch 2.54mm



PH1RD/U XX - 2 XX - L/U
1 2 3

1.H=1.5/1.7mm 2.No. of Contacts(02~40)
H=2.5mm 2.No. of Contacts(02~50)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PH1RD/U XX - 1 XX - L/U
1 2 3

1.H=1.5/1.7mm 2.No. of Contacts(02~40)
H=2.5mm 2.No. of Contacts(02~50)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm



PH1DR - 2 XX - L/U
1 2

H=2.5mm
1.No. of Contacts(02~40)
2.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PH1DR - 1 XX - L/U
1 2

H=2.5mm
1.No. of Contacts(02~40)
2.RoHS + PBT/Nylon 6T

Pitch 2.54mm



Pressing Fit Type
PH1FS - 2 XX - L
1 2

H=2.5mm
1.No. of Contacts(02~40)
2.RoHS + PBT

Pitch 2.54mm



Pressing Fit Type
PH1FS - 1 XX - L
1 2

H=2.5mm
1.No. of Contacts(02~40)
2.RoHS + PBT

Pitch 2.54mm



PH1S XX - 2 XX - L/U
1 2 3

1.H=1.5/1.7mm 2.No. of Contacts(02~40)
H=2.5mm 2.No. of Contacts(02~50)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PH1S XX - 1 XX - L/U
1 2 3

1.H=1.5/1.7mm 2.No. of Contacts(02~40)
H=2.5mm 2.No. of Contacts(02~50)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm



PH1D XX - 2 XX - L/U
1 2 3

1.H=1.5/1.7mm 2.No. of Contacts(02~40)
H=2.5mm 2.No. of Contacts(02~50)
3.RoHS + PBT/Nylon 6T

CONNECTORS MANUFACTURER



2 * 10
P in Header / Female 2.54 mm
RoHS


Pitch 2.54mm



PH1D XX - 1 XX - L/U
1 2 3

1.H=1.5/1.7mm 2.No. of Contacts(02~40)
H=2.5mm 2.No. of Contacts(02~50)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm



PH1S/R - 3 XX - L/U
1 2 3

1.S: Straight R:R/A
2.H=2.5mm No. of Contacts(02~50)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PH1D - 3 XX - L/U
1 2

H=2.5mm
1.No. of Contacts(02~50)
2.RoHS + PBT/Nylon 6T

Pitch 2.54mm
Pressing Fit Type



BH1FS - XX - L
1 2

1.No. of Contacts(10~64)
2.RoHS + PBT


Pitch 2.54mm



BH1X - XX - L/U
1 2 3

1.S: Straight M: SMT R:R/A
2.No. of Contacts(06~64)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



BH1AX - XX - L/U
1 2 3

1.S: Straight R:R/A
2.No. of Contacts(06~64)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm



BH1EX - XX - L/U
1 2 3

1.S: Straight M: SMT
2.No. of Contacts(06~64)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



Pressing Fit Type
EDH1FS - XX - L
1 2

1.No. of Contacts(10~64)
2.RoHS + PBT


Pitch 2.54mm



EDH1XSL - XX - L
1 2 3

1.S: Straight R:R/A
2.No. of Contacts(06~64)
3.RoHS + PBT


Pitch 2.54mm



EDH1X - XX - L/U
1 2 3

1.S: Straight M: SMT R:R/A
2.No. of Contacts(10~64)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PS1M35 - 2 XX - U
1 2 3

H=3.55mm
2.No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 2.54mm



PS1B35 - 2 XX - L/U
1 2 3

1.H=3.55mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm **Y Contact**



PS1S 35 - 1/2 XX - L/U
1 2 3

1.H=3.55mm 1 & 2 rows
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm **Triple Contact**



PS1S 35 A - 2 XX - L/U
1 2 3

1.H=3.55mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PS1M 50 - 2 XX - U
1 2 3

1.H=5.0mm
2.No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 2.54mm



PS1M 50 - 1 XX - U
1 2 3

1.H=5.0mm
2.No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 2.54mm



PS1S 50 - 1/2 XX - L/U
1 2 3

1.H=5.0mm 1 & 2 rows
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PS1R 50 - 1 XX - L/U
1 2 3

1.H=5.0mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PS1B 50 - 2 XX - L/U
1 2 3

1.H=5.0mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PS1B 50 - 1 XX - L/U
1 2 3

1.H=5.0mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PS1R 57 - 1/2 XX - L/U
1 2 3

1.H=5.7mm 1 & 2 rows
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PS1S 57 - 1/2 XX - L/U
1 2 3

1.H=5.7mm 1 & 2 rows
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PS1S 68 - 1/2 XX - L/U
1 2 3

1.H=6.8mm 1 & 2 rows
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm



PS1S 68 A - 2 XX - L/U
1 2 3

1.H=6.8mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

CONNECTORS MANUFACTURER




2
*
12

P in Header / Female 2.54 mm



RoHS


Pitch 2.54mm



PS1M 71 - 2 XX - U
1 2 3

1.H=7.1mm
2.No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 2.54mm



PS1M 71 - 1 XX - U
1 2 3

1.H=7.1mm
2.No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 2.54mm



PS1S 71 - 1 XX - L/U
1 2 3

1.H=7.1mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PS1S 71 - 1 XX - L/U
1 2 3

1.H=7.1mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PS1M 85 - 2 XX - U
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 2.54mm



PS1M 85 - 1 XX - U
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 2.54mm



PS1TM 85 - 2 XX - U
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 2.54mm



PS1TM 85 - 1 XX - U
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 2.54mm
Pressing Fit



PS1FS 85 - 2 XX - L
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + PBT


Pitch 2.54mm
Pressing Fit



PS1FS 85 - 1 XX - L
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + PBT


Pitch 2.54mm



PS1R 85 - 1/2 XX - L/U
1 2 3

1.H:8.5mm 1 & 2 rows
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm



PS1S 85 - 1/2 XX - L/U
1 2 3

1.H:8.5mm 1 & 2 rows
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm

PS1R 85 B - 2 XX - L/U
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm

PS1S 85 B - 2 XX - L/U
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm

PS1T 85 - 2 XX - L/U
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm

PS1T 85 - 1 XX - L/U
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm

PS1R 85 - 3 XX - L/U
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm

PS1S 85 - 3 XX - L/U
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm
Predding Fit

PS1FE - 1/2 XX - L
1 2

1 & 2 Row
1.No. of Contacts(02~40)
2.RoHS + PBT

Pitch 2.54mm
Pin=0.64X0.6mm

PS1E - 1/2/3 XX - L/U
1 2

1 & 2 & 3 Row
1.No. of Contacts(02~40)
2.RoHS + PBT/Nylon 6T

Pitch 2.54mm
Pin=0.6X0.4mm

PS1AE - 1/2/3 XX - L/U
1 2

1 & 2 & 3 Row
1.No. of Contacts(02~40)
2.RoHS + PBT/Nylon 6T

Pitch 2.54mm

PS1F 85 - 2 XX - L/U
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm

PS1F 85 - 1 XX - L
1 2 3

1.H=8.5mm
2.No. of Contacts(02~40)
3.RoHS + PBT

Pitch 2.54mm

PS1M 110 - 2 XX - U
1 2 3

1.H=11.0mm
2.No. of Contacts(02~40)
3.RoHS + Nylon 6T

CONNECTORS MANUFACTURER




2
*
14

P in Header / Female 2.54 - 4.2 mm



RoHS


Pitch 2.54mm



PS1S 110 - 2 XX - L/U
1 2 3

1.H=11.0mm
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T


Pitch 2.54mm



PS1 MS - 1/2 XX - U
1 2 3

1.SMT Type
2.No. of Contacts(02~40)
3.RoHS + Nylon 6T


Pitch 2.54mm



PS1 RS - 1/2 XX - L/U
1 2 3

1.Right Angle Type
2.No. of Contacts(02~40)
3.RoHS + PBT/Nylon 6T

Pitch 2.54mm



MJ1 X - X - L
1 2 3

1.B:Brass P:Phosphor Bronze
2.A:Close 6.5mm B:Open 6.0mm
C:Open 4.5mm D:With handle 13.75mm
F:Close 6.0mm G:Close 8.5mm H:Open 8.0mm
3.RoHS + PBT(D Type RoHS + Nylon 66)

Pitch 2.54mm



MJ1 X - E XX - L
1 2 3

1.B:Brass P:Phosphor Bronze
2.No. of Contacts(02~13)
3.RoHS + PBT


Pitch 2.54mm



PH1SMJ X - X 1/2 XX - L/U
1 2 3 4

1.B:Brass P:Phosphor Bronze
2.A:Close 6.5mm B:Open 6.0mm
C:Open 4.5mm D:With handle 13.75mm
F:Close 6.0mm G:Close 8.5mm H:Open 8.0mm
3.No. of Contacts(02~10)
4.RoHS + PBT/Nylon 6T


Pitch 3.96mm



PH396 R 32 - 1 XX - U
1 2 3

1.H=3.2mm
2.No. of Contacts(01~24)
3.RoHS + LCP


Pitch 3.96mm



PH396 S 32 - 1 XX - U
1 2 3

1.H=3.2mm
2.No. of Contacts(01~24)
3.RoHS + LCP


Pitch 3.96mm



PS396 M 89 - 1 XX - U
1 2 3

1.H=8.9mm
2.No. of Contacts(02~24)
3.RoHS + LCP


Pitch 3.96mm



PS396 S 89 - 1 XX - U
1 2 3

1.H=8.9mm
2.No. of Contacts(02~24)
3.RoHS + LCP


Pitch 4.2mm



PH42M25 - 2 XX - U
1 2 3

1.SMT Type
2.No. of Contacts(02~16)
3.RoHS + Nylon 6T


Pitch 4.2mm



PH42S25 - 2 XX - U
1 2 3

1.Straight Type
2.No. of Contacts(02~16)
3.RoHS + PBT/Nylon 6T


Pitch 5.08mm



PH8M25 - 1 XX - U
1 2 3

1.SMT Type
2.No. of Contacts(02~20)
3.RoHS + LCP


Pitch 5.08mm



PH8RU25 - 1 XX - U
1 2 3

1.R/A U Type
2.No. of Contacts(02~20)
3.RoHS + LCP


Pitch 5.08mm



PH8S25 - 1 XX - U
1 2 3

1.Straight Type
2.No. of Contacts(02~20)
3.RoHS + LCP

Pitch 5.08mm



PH8D25 - 1 XX - U
1 2 3

1.Stack Straight Type
2.No. of Contacts(02~20)
3.RoHS + LCP

Pitch 5.08mm



PS8M89 - 1 XX - U
1 2 3

1.SMT Type
2.No. of Contacts(02~20)
3.RoHS + LCP

Pitch 5.08mm



PS8S89 - 1 XX - U
1 2 3

1.Straight Type
2.No. of Contacts(02~20)
3.RoHS + LCP

